



Work Order (Bid Form)



WORK ORDER INFORMATION

Work Order Name: WO/90009MD1101/1

Work Order Type: Weatherization

Audit Name: 90009MD1101

CLIENT INFORMATION

Client Name:

Address:

Client ID: 90009MD1101

, 37204

Alt. Client ID: DAVIDSON

AGENCY INFORMATION

Agency: Metropolitan Development Housing Agency

Agency Phone: (615) 252-8500

Address: 701 s. 6th St.

Fax: (615) 252-8533

Nashville, TN 37206

Email Address: Rlayman@nashville-mdha.org

Agency Contact: Jsummers

Work Phone: (615) 473-2343

Cell Phone:

Email Address: jsummers@united.net

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

SITE BUILT IN 1945, BRICK EXTERIOR

Client Name:

Client ID: 90009MD1101

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD1101/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 7

Measures

Measure 1 Infiltration Redctn		Components	Inspected
Comment INFILTRATION REDUCTION MEASURES:			<input type="checkbox"/>
1.) SEAL PLUMBING PENETRATIONS KITCHEN AND BATH.			
2.) REMOVE BUILT IN AC UNIT IN EAST SIDE WALL, SEAL HOLE WITH WOOD SIDING, INSULATION, DRYWALL, SEAL EDGES & PAINT INTERIOR AND EXTERIOR. 30 X 24			
3.) WEATHERSTRIP DR1, DR2, DR3, DR5			
4.) REPLACE BROKEN GLASS PANE ON WD8 (EXTERIOR) 58 X 52			
5.) REGLAZE WD9-UP			
8.) CAULK AND SEAL ALL WINDOW FRAMES AND SILLS, INTERIOR AND EXTERIOR (12 widnows)			
MATERILAS:			
1.) WEATHERSTRIPPING			
2.) SPRAY FOAM			
3.) CLEAR AND WHITE CAULK			
4.) SIDIING 30 X 24			
5.) DRYWALL 30 X 24			
6.) INSULATED BATT 30 X 24			
7.) PAINT			
8.) GLASS PANE 58 X 52			
9.) WINDOW GLAZING			
WINDOW NOTES:			
WD1N: 20 X 53, (2 SIDE WINDOWS OF FRONT BAY WIINDOW) CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD2S: 30 X 53 (CENTER OF BAY WINDOW) CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD3S: 40 X 53, CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD4W: 30 X 57, (2 WINDOWS WEST SIDE OF HOUSE) CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD5S: 27 X 37 (LEFT OF BACK DOOR) CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD6S: 27 X 37, (2 WINDOWS RIGHT OF BACK DOOR) CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD7E: 30 X 52, (EAST SIDE OF HOUSE) CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD8N: 58 X 52, (FRONT OF HOUSE, LEFT OF FRONT DOOR) REPLACE BROKEN EXTERIOR PANE. CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			
WD9W-UP: 32 X 59, (ATTIC WINDOW) REGLAZE, INSTALL CAULK AND SEAL FRAMES, INTERIOR AND EXTERIOR.			

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Su	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Client Name:

Client ID: 90009MD1101

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD1101/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 7

Other Detail

Measure Sub Total: **Sub Total:**

Field Notes:**Measure 2 Attic Ins. R-38****Components A1****Inspected****Comment** NONE EXISTS, INSTALL TO 14-16 "

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1360	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

Measure Sub Total: **Sub Total:**

Field Notes:

Client Name:

Client ID: 90009MD1101

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD1101/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 7

Measure 3 DWH Pipe Insulation**Components****Inspected****Comment** FIRST 5 FT☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Other	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 DWH Tank Insulation****Components****Inspected****Comment** 40 Gal WH☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Other	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 90009MD1101

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD1101/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 7

Measure 5 Storm Windows**Components** WD9-W-UP**Inspected****Comment** INSTALL NEW STORM NONE EXISTING 32 X 59☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window	SqFt	13.11	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Storm Window	SqFt	13.11	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Other	Storm Window	Each Window	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 Floor Ins. R-19****Components** F1**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1360	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 90009MD1101

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD1101/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 7

Measure 7 CO Monitor is Needed**Components****Inspected****Comment** NONE EXIST☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 8 INSTALL NEW DIGITAL THERMOSTAT****Components****Inspected****Comment** OLD THERMOSTAT NOT OPERATIONAL☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	DIGITAL THERMOSTAT	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 90009MD1101

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD1101/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 7

Measure 9 Smoke Detector is Needed**Components****Inspected****Comment** NONE EXIST☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 90009MD1101

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD1101/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.6.0

Page 7 of 7